



**VOLKSWAGEN PASSAT VARIANT: 1LKZ177**

|                                    |                          |              |                                     |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnnumber:                        | <b>WVWZZZ3CZGE084580</b> | Versionname: | <b>1.6 TDI MSQ VARIANT HIGHLINE</b> |
| First Registrationdate:            | <b>15/10/2015</b>        | Fiscalpower: |                                     |
| Expertise Mileage:                 | <b>120370</b>            | Power Kw:    | <b>88</b>                           |
| Bodytype:                          |                          | Body color:  | <b>Brown</b>                        |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                           |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2627</b>                         |
| Number of doors:                   | <b>5</b>                 |              |                                     |
| Number of seats:                   | <b>5</b>                 |              |                                     |
| Number head rests:                 | <b>5</b>                 |              |                                     |
| Rims summer:                       | <b>Aluminium</b>         |              |                                     |
| Category:                          | <b>Passenger Car</b>     |              |                                     |
| Oil level:                         | <b>OK</b>                |              |                                     |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                     |

**Options**

|                                |  |
|--------------------------------|--|
| Windows electric F             | Central consol F                               |
| Windows electric R             | Luggage cover                                  |
| Cruise Control                 | Front parking sensors                          |
| Steering wheel multifunctional | Rear parking sensors                           |
| Seats F heated                 | Type of Tow bar                                |
| Radio multimedia               | <b>Tow bar fixed</b>                           |
| Type of headlighting           | <b>Headlighting Halogen</b>                    |
| Type of GPS                    | <b>GPS big screen color</b>                    |
| Type of Lining                 | <b>Lining artificial leather and alcantara</b> |
| Type of climate control        | <b>Autom climate control</b>                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |       |                   |
|----------------------------------|-------|-------|-------------------|
| <b>215/55/17/94 W LightMetal</b> |       |       |                   |
| Winter tyres:                    | Fr.L. | Fr.R. | Continental: 2 mm |
|                                  | Re.L. | Re.R. | Continental: 4 mm |

**Assistance equipment**

|  |          |
|--|----------|
| Number of charging cables (normal)       | <b>0</b> |
| Number of charging cables (rapid charge) | <b>0</b> |

|   |                |
|---|----------------|
| Total cost ex VAT                                       | <b>1933,92</b> |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b>  |



Internal Boot Lining L, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Trunk lid covering R, Scratch(es), E - Replace 88,00



Windscreen, Scratch(es), E - Replace 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Headlight R, Scratch(es), E - Replace 396,00



Bumper grille, Broken, E - Replace

32,40



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Internal Boot Lining R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Roof, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Tailgate, Scratch(es), Acceptable

0,00

*No pictures to display*