



**AUDI Q5: 1HFG300**

Vinnumber:	<b>WAUZZZ8R0FA012086</b>	Versionname:	<b>Q5 S-tronic 163PK Aut.</b>
First Registrationdate:	<b>7/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>192515</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>DEPUIS 60 0KM</b>	Parking lot:	<b>1333</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/17/108 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Michelin: 8 mm</b>	Fr.R.	<b>Michelin: 8 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Compressor	<b>Yes</b>
		Jack	<b>Yes</b>

Total cost ex VAT	696,66
Front end, Not original part, P - Check	0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 350,16



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Stain, Cleaning 25,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Reflector, Broken, E - Replace 104,70



Luggage space cover, Incomplete, Forfeit 9,80



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight R , Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), E - Replace 132,00



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F L, Scratch(es), It - Spot repair 75,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

