


BMW 1 HATCH: 1TBS037

Vinnnumber:	WBA1V910X0V965554	Versionname:	116d EfficientDynamics Edition (85 kW)
First Registrationdate:	18/09/2017	Fiscalpower:	
Expertise Mileage:	51725	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3324
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	371,00
-------------------	---------------

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet cable F, Missing, E - Replace 120,00



Door R R, Dent(s), PDR - Paintless dent repair 63,00



Mirror side blinker L, Broken, E - Replace 30,00



Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), Acceptable 0,00

No pictures to display