



**BMW 1 HATCH: 1RKP332**

Vinnumber:	<b>WBA1V910205G94220</b>	Versionname:	<b>1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)</b>
First Registrationdate:	<b>13/01/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>49688</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3428</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**









<b>205/55/16/92 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>978,20</b>
Bumper R, Not original part, E - Replace	<b>49,00</b>



Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s), PDR - Paintless dent repair	63,00
	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Engine protective plate, Deformed / Strained, E - Replace	62,00
	
Roof, Dent(s), PDR - Paintless dent repair	320,40
	
Bumper R, Bad repair, LI - Repair and paint (complete)	0,00
	
Wing R R, Dent(s), PDR - Paintless dent repair	63,00
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing R L, Bad repair, LI - Repair and paint (complete)	0,00
	
Rearlight R , Crack, E - Replace	114,00
	
Wing F R, Bad repair, LI - Repair and paint (complete)	0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

