


CITROEN GRAND C4 PICASSO: 1NBE754

Vinnumber:	VF73ABHXTFJ884228	Versionname:	1.6 BLUEHDI 115 S/S BUSINESS GPS AUTO
First Registrationdate:	11/01/2016	Fiscalpower:	
Expertise Mileage:	168612	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3315
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	881,36
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper F, Crack, Le - Replace and paint

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Windscreen, Stone chip(s), E - Replace

0,00




Wing R R, Bad repair, LI - Repair and paint (complete)

0,00



Bonnet, Bad repair, LI - Repair and paint (complete)

0,00



Wing F L, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Sill outer R, Dent(s), Le - Replace and paint

0,00



Maintenance, Maintenance, Execute

0,00

No pictures to display

Headlight L, Broken, E - Replace

396,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

