



FORD S-MAX: 1LRS658

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | WF0JXXWPCJFS23030 | Versionname: | 2.0 TDCI 110KW S/S BUSINESS ED+ |
| First Registrationdate: | 17/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 131957 | Power Kw: | 110 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3408 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | SD | Seats electric F R | |
| GPS storage | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | No Tow bar |
| Seats F heated | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 235/55/17/99 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 221,28 |
|-------------------|---------------|

| | |
|----------------------------------|-------------|
| Seat F L compl, Worn, Acceptable | 0,00 |
|----------------------------------|-------------|

No pictures to display

| | |
|---|-------------|
| Door R R, Dent(s) and scratch(es), Acceptable | 0,00 |
|---|-------------|

No pictures to display

| | |
|---|---------------|
| Internal Boot Lining L, Scratch(es), Smart repair | 110,64 |
|---|---------------|



| | |
|---|--------|
| Centre console, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tires, Not original part, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Steering wheel, Worn, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door panel R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Internal Boot Lining R, Scratch(es), Smart repair | 110,64 |



| | |
|---|------|
| Trunk lid covering R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Ignition key, Worn, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Ceiling, Stain, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rear bulkhead lining, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| MOT Certificate, Missing, Acceptable | 0,00 |

