


SKODA Octavia: 1GBG436

Vinnumber:	TMBJG7NE1E0108731	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	13/12/2013	Fiscalpower:	
Expertise Mileage:	126016	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3119
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment


Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1750,65
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35




Rear spoiler, Hail damage, LI - Repair and paint (complete)

0,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Roof, Hail damage, LI - Repair and paint (complete)

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)


211,80



Bonnet, Hail damage, PDR - Hail

0,00





Ignition key, Missing, E - Replace 150,00

No pictures to display

Luggage space cover, Missing, E - Replace 240,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display