



**BMW 5 TOURING: 1LDS632**

Vinnumber:	WBA5L51070G089398	Versionname:	2.0 520D (120KW) XDRIVE AUTO TOURING
First Registrationdate:	31/08/2015	Fiscalpower:	
Expertise Mileage:	134467	Power Kw:	120
Bodytype:		Body color	White
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2709
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

**Options**

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Tow bar fixed
Type of GPS	
Type of Lining	
Type of climate control	
	Headlighting Xenon
	GPS big screen color
	Lining leather
	Autom climate control

**Limited Technical Inspection**

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

**Degree of wear**

Winter tyres:	245/45/18/100 V LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

**Assistance equipment**

Runflat		Yes
Total cost ex VAT		703,72
Bumper F, Scratch(es), LI - Repair and paint (complete)		254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display

Door panel F L, Worn, Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00




Inner seat cover L, Broken, E - Replace

69,56



Rear window, Scratch(es), E - Replace

0,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

