



BMW X1: 1JAP454

Vinnumber:	WBAVY11050VZ27112	Versionname:	X1 sDrive16d 116PK
First Registrationdate:	18/11/2014	Fiscalpower:	
Expertise Mileage:	71381	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1110
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/92 MS LightMetal				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	2285,67
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing trim R R, Scratch(es), E - Replace 84,00



Towhook, Missing, Forfeit 15,00



Bumper Trim F, Scratch(es), Smart repair 110,64



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearlight L, Broken, E - Replace 114,00



Wing R R, Chemical pollution, LI - Repair and paint (complete) 308,20



Wing moulding F R, Scratch(es), E - Replace 14,40



Bumper F, Scratch(es), It - Spot repair 115,56



Bumper trim R, Scratch(es), Smart repair 110,64



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display

Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

