



FIAT SCUDO: DN7308

Vinnumber:	ZFA27000064371778	Versionname:	2.0 MULTIJET 16V 94KW LH1 12Q DE LUX
First Registrationdate:	12/01/2016	Fiscalpower:	
Expertise Mileage:	86767	Power Kw:	94
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1227
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Rear parking sensors	
Windows electric F			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/103 T Steel			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1764,46

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 328,88





Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 361,13



Wing trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 395,40



Bumper R, Hole, E - Replace 329,40



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 327,15



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror L complete, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 22,50

