


**FIAT 500X: EH1986**

|                                    |                         |              |                        |
|------------------------------------|-------------------------|--------------|------------------------|
| Vinnumber:                         | <b>ZFA334000P399854</b> | Versionname: | <b>1.6 MJET LOUNGE</b> |
| First Registrationdate:            | <b>30/10/2015</b>       | Fiscalpower: |                        |
| Expertise Mileage:                 | <b>113591</b>           | Power Kw:    | <b>85</b>              |
| Bodytype:                          |                         | Body color:  | <b>White</b>           |
| Gearbox:                           | <b>MAN 5 VIT</b>        | Paint type:  | <b>Opaque</b>          |
| Transmission:                      | <b>Front</b>            | Rims summer: | <b>Aluminium</b>       |
| Fueltype:                          | <b>Diesel</b>           | Oil level:   | <b>OK</b>              |
| Battery functioning:               | <b>Yes</b>              | Parking lot: | <b>3603</b>            |
| Number of doors:                   | <b>5</b>                |              |                        |
| Number of seats:                   | <b>5</b>                |              |                        |
| Number head rests:                 | <b>4</b>                |              |                        |
| Rims summer:                       | <b>Aluminium</b>        |              |                        |
| Category:                          | <b>Passenger Car</b>    |              |                        |
| Oil level:                         | <b>OK</b>               |              |                        |
| Registration Certificate Car (BE): | <b>No</b>               |              |                        |

**Options**

|                                |                                       |                      |
|--------------------------------|---------------------------------------|----------------------|
| GPS storage                    |                                       | Central consol F     |
| GPS storage                    | <b>HD</b>                             | Luggage cover        |
| Windows electric F             |                                       | Rear parking sensors |
| Windows electric R             |                                       |                      |
| Cruise Control                 |                                       |                      |
| Steering wheel multifunctional |                                       |                      |
| Radio multimedia               |                                       |                      |
| Type of headlighting           | <b>Headlighting LED</b>               |                      |
| Type of GPS                    | <b>GPS big screen color</b>           |                      |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |                      |
| Type of climate control        | <b>Autom climate control</b>          |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/45/18/95 V LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Michelin: 4 mm</b>    | Fr.R. | <b>Michelin: 4 mm</b>    |
|               | Re.L.                            | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 4 mm</b> |

**Assistance equipment**

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                                                              |        |
|--------------------------------------------------------------|--------|
| Total cost ex VAT                                            | 487,80 |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00  |



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s), PDR - Paintless dent repair 82,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Luggage space cover, Missing, Forfeit 25,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display