



**AUDI A4 AVANT: 1JVX620**

|                                    |                          |              |                            |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber:                         | <b>WAUZZZ8K1FA102656</b> | Versionname: | <b>2.0 TDI ULTRA 100KW</b> |
| First Registrationdate:            | <b>10/03/2015</b>        | Fiscalpower: |                            |
| Expertise Mileage:                 | <b>142919</b>            | Power Kw:    | <b>100</b>                 |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Grey</b>           |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>             |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>4332</b>                |
| Battery functioning:               | <b>Yes</b>               |              |                            |
| Number of doors:                   | <b>5</b>                 |              |                            |
| Number of seats:                   | <b>5</b>                 |              |                            |
| Number head rests:                 | <b>5</b>                 |              |                            |
| Rims summer:                       | <b>Aluminium</b>         |              |                            |
| Category:                          | <b>Passenger Car</b>     |              |                            |
| Oil level:                         | <b>OK</b>                |              |                            |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                            |

**Options**

|                                |                                 |
|--------------------------------|---------------------------------|
| Radio CD                       | Central consol F                |
| GPS storage                    | Luggage cover                   |
| GPS storage                    | <b>CD</b> Front parking sensors |
| Windows electric F             | Rear parking sensors            |
| Windows electric R             | Type of Tow bar                 |
| Cruise Control                 | <b>Tow bar fixed</b>            |
| Steering wheel multifunctional |                                 |
| Seats F heated                 |                                 |
| Type of headlighting           | <b>Headlighting Xenon</b>       |
| Type of GPS                    | <b>GPS big screen color</b>     |
| Type of Lining                 | <b>Lining leather</b>           |
| Type of climate control        | <b>Autom climate control</b>    |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                     |       |                     |
|---------------|-----------------------------------|---------------------|-------|---------------------|
|               | <b>205/60/16/92 MS LightMetal</b> |                     |       |                     |
| Winter tyres: | Fr.L.                             | <b>Kleber: 4 mm</b> | Fr.R. | <b>Kleber: 4 mm</b> |
|               | Re.L.                             | <b>Kleber: 5 mm</b> | Re.R. | <b>Kleber: 5 mm</b> |

**Assistance equipment**

|                                      |            |      |               |
|--------------------------------------|------------|------|---------------|
| Emergency spare wheel                | <b>Yes</b> | Jack | <b>Yes</b>    |
| Total cost ex VAT                    |            |      | <b>178,56</b> |
| Wing R R, Scratch(es), Acceptable    |            |      | <b>0,00</b>   |
| <i>No pictures to display</i>        |            |      |               |
| Rear window, Scratch(es), Acceptable |            |      | <b>0,00</b>   |



Door R R, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Scratch(es), It - Spot repair

115,56



Door R L, Dent(s), Acceptable

0,00

*No pictures to display*

Door R L, Dent(s), PDR - Paintless dent repair

63,00



Wing F L, Scratch(es), Acceptable

0,00

*No pictures to display*