



PEUGEOT PARTNER TEPEE: 1TPX442

Vinnumber:	VF37JBHZMHJ903497	Versionname:	1.6 BlueHDi 88kW S&S Tepee Active
First Registrationdate:	9/01/2018	Fiscalpower:	
Expertise Mileage:	185298	Power Kw:	88
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3716
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Rear parking sensors	
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	No
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/15/92 MS Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1733,38
-------------------	----------------

Bumper F, Scratch(es), It - Spot repair	115,56
-----------------------------------------	---------------



Boot carpet, Hole, Forfeit	246,00
----------------------------	---------------



Reversible boot mat, Hole, E - Replace

59,60



Boot cover, Missing, E - Replace

37,50



Door trim F R, Scratch(es), E - Replace

91,50



Door trim R R, Scratch(es), E - Replace

91,50



Wing R R, Dent(s), LI - Repair and paint (complete)

231,15



Door R R, Dent(s), LI - Repair and paint (complete)

238,76



Sill outer L, Scratch(es), It - Spot repair

115,56



Bumper R, Dent(s), Le - Replace and paint

506,25

