



PEUGEOT 308: 1LLH747

Vinnumber:	VF3LBBHX3FS263553	Versionname:	1.6 BLUEHDI 85KW S/S ALLURE
First Registrationdate:	20/10/2015	Fiscalpower:	
Expertise Mileage:	81699	Power Kw:	85
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4609
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 815,50

Bonnet, Scratch(es), Acceptable 0,00



Roof, Dent(s), Acceptable

0,00



Alloy rim R L polished, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Steering wheel, Worn, Acceptable

0,00



Alloy rim F R polished, Scratch(es), I - Repair

155,00



Door F L, Scratch(es), Acceptable

0,00




Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50




Alloy rim R R polished, Scratch(es), I - Repair

155,00



Alloy rim F L polished, Scratch(es), I - Repair 155,00



Wing R L, Dent(s), Acceptable 0,00



Wing R R, Dent(s), Acceptable 0,00



Mats, Worn, E - Replace 40,00

