



FORD MONDEO CLIPPER: 1NST946

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WF0FXXWPCFGA22453 | Versionname: | 2.0 TDCI 110KW S/S ECONETIC BUSINESS ED+ |
| First Registrationdate: | 18/04/2016 | Fiscalpower: | |
| Expertise Mileage: | 119562 | Power Kw: | 110 |
| Bodytype: | | Body color: | Red |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4428 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--|
| Radio CD | | Seats electric F L | |
| GPS storage | | Seats electric F R | |
| GPS storage | SD | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 235/50/17/100 V LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-------------------|---------------|
| Total cost ex VAT | 913,86 |
|-------------------|---------------|

| | |
|-------------------------------|-------------|
| Wing R R, Dent(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

| | |
|-------------------------------------|--------------|
| Brand badge R, Missing, E - Replace | 64,20 |
|-------------------------------------|--------------|



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable

0,00

No pictures to display