



BMW 3 GRAN TURISMO: 1NDX137

Vinnumber:	WBA8Y51090G436888	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	1/02/2016	Fiscalpower:	
Expertise Mileage:	83921	Power Kw:	100
Bodytype:		Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4115
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			95,00
Bumper R, Scratch(es), 67 - Polish			0,00
No pictures to display			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00

