



MINI : 1NES321			
Vinnumber:	WMWXN310303B55267	Versionname:	1.5 COOPER D
First Registrationdate:	5/02/2016	Fiscalpower:	
Expertise Mileage:	102045	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2524
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
GPS storage		Sun Roof electric	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/45/17/88 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	430,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s), PDR - Paintless dent repair 82,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair 63,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display