



**PEUGEOT 208: 1NFJ259**

Vinnumber:	<b>VF3CC8HY6FT248072</b>	Versionname:	<b>1.6 BLUEHDI 74KW S/S 79G ACTIVE</b>
First Registrationdate:	<b>11/02/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>130881</b>	Power Kw:	<b>74</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3719</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 T Steel</b>			
Winter tyres:	Fr.L.	<b>Semperit: 4 mm</b>	Fr.R.	<b>Semperit: 4 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1216,58</b>
-------------------	----------------

Wheel cover F R, Missing, E - Replace	<b>24,00</b>
---------------------------------------	--------------



Steering wheel, Worn, Acceptable

0,00



Door F L, Dent(s), PDR - Paintless dent repair

82,80



Wheel cover F L, Scratch(es), E - Replace

24,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Bonnet, Dent(s), Acceptable

0,00

*No pictures to display*

Door R L, Dent(s), Acceptable

0,00

*No pictures to display*

Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*

Wheel cover R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F R, Dent(s), PDR - Paintless dent repair

82,80



Roof, Chemical pollution, LI - Repair and paint (complete)

481,20



Tailgate, Dent(s), LI - Repair and paint (complete) 289,34



Wing R R, Dent(s), PDR - Paintless dent repair 63,00

