



PEUGEOT 308 SW: 1JXJ944

Vinnumber:	VF3LCBHXHFS051358	Versionname:	1.6 BLUEHDI 85KW S/S ALLURE
First Registrationdate:	12/03/2015	Fiscalpower:	
Expertise Mileage:	198768	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2323
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	95,00
-------------------	--------------

Alloy Rims (all), Rust, Acceptable	0,00
------------------------------------	-------------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim R, polished, Scratch(es), H. Damage and paint (complete)	05,00
--	--------------

Απογ ριμ κ λ ροισηα, scratch(es), LI - repair and paint (complete)

95,00



Maintenance book, Missing, E - Replace

0,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display