



OPEL COMBO: 1RDL015

Vinnumber:	W0L6ZZU1AH9606341	Versionname:	1.3 CDTi 70KW 2.0T L1H1
First Registrationdate:	23/11/2016	Fiscalpower:	
Expertise Mileage:	55201	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEKLOP BIJ STUREN	Parking lot:	3826
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	No
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/92 H Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	636,20
-------------------	--------

Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door panel F L, Scratch(es), E - Replace	91,50
--	-------



Bumper grille. Not original part. E - Replace 30,30

Bumper grnd, not original part, E - Replace

0,00



Trunk door R L, Dent(s), LI - Repair and paint (complete)

185,00



Trunk door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), E - Replace

329,40



Maintenance, Maintenance, Execute

0,00

No pictures to display