



**TOYOTA AVENSIS TOURING SPORTS: 1NTS832**

Vinnumber:	<b>SB1ET76L60E012703</b>	Versionname:	<b>2.0 D-4D PREMIUM</b>
First Registrationdate:	<b>25/04/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>109897</b>	Power Kw:	<b>105</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>CONTROLEREN</b>	Parking lot:	<b>3209</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>HD</b>	Seats electric F R	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>Tow bar removable</b>
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/18/95 V LightMetal</b>				
Winter tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Kleber: 7 mm</b>	Re.R.	<b>Kleber: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>610,56</b>
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Bumper R, Repaired, Acceptable

0,00



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), It - Spot repair

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Door F R, Dent(s), Acceptable

0,00



Tyre R R, Tear, E - Replace

132,00



Wing R R, Dent(s), Acceptable

0,00



Aerial, Broken, E - Replace

15,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Not original part, Acceptable

0,00



Rearlight L, Scratch(es), 67 - Polish

0,00



Wing F L, Scratch(es), Acceptable

0,00

