


SKODA OCTAVIA: 1PVP475

Vinnumber:	TMBAG9NEXH0065524	Versionname:	1.6 CRTDI 81KW GREENTEC STYLE
First Registrationdate:	29/09/2016	Fiscalpower:	
Expertise Mileage:	75997	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1524
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Seats electric F L
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather and alcantara
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	464,80
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Dent(s), LI - Repair and paint (complete)

211,80



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

