



**VOLKSWAGEN CADDY: 1PSX487**

|                                    |                                 |              |  |
|------------------------------------|---------------------------------|--------------|--|
| Vinnumber:                         | <b>WV2ZZZ2KZH029153</b>         | Versionname: | <b>2.0 CRTDI 75KW SCR BMT MAXI TRENDLINE</b> |
| First Registrationdate:            | <b>9/09/2016</b>                | Fiscalpower: |  |
| Expertise Mileage:                 | <b>236349</b>                   | Power Kw:    | <b>75</b>                                    |
| Bodytype:                          |                                 | Body color:  | <b>Grey</b>                                  |
| Gearbox:                           | <b>MAN 5 VIT</b>                | Paint type:  | <b>Metalic</b>                               |
| Transmission:                      | <b>Front</b>                    | Rims summer: | <b>Steel</b>                                 |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                    |
| Maintenance:                       | <b>OK</b>                       | Parking lot: | <b>3813</b>                                  |
| Maintenance:                       | <b>OVER 27500 KM</b>            |              |  |
| Battery functioning:               | <b>Yes</b>                      |              |  |
| Number of doors:                   | <b>5</b>                        |              |  |
| Number of seats:                   | <b>5</b>                        |              |  |
| Number head rests:                 | <b>5</b>                        |              |  |
| Rims summer:                       | <b>Steel</b>                    |              |  |
| Category:                          | <b>Light Commercial Vehicle</b> |              |  |
| Oil level:                         | <b>OK</b>                       |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |  |

**Options**

|                         |                               |                      |                   |
|-------------------------|-------------------------------|----------------------|-------------------|
| Windows electric F      |                               | Central consol F     |                   |
| Radio multimedia        |                               | Rear parking sensors |                   |
| Type of headlighting    | <b>Headlighting Halogen</b>   | Type of Tow bar      | <b>No Tow bar</b> |
| Type of Lining          | <b>Lining fabrics</b>         |                      |                   |
| Type of climate control | <b>Manual climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                     |       |                     |
|---------------|-----------------------------|---------------------|-------|---------------------|
|               | <b>205/55/16/94 H Steel</b> |                     |       |                     |
| Winter tyres: | Fr.L.                       | <b>Kleber: 5 mm</b> | Fr.R. | <b>Kleber: 5 mm</b> |
|               | Re.L.                       | <b>Kleber: 4 mm</b> | Re.R. | <b>Kleber: 4 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Spare wheel                              | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                                     |               |
|-------------------------------------|---------------|
| Total cost ex VAT                   | <b>721,96</b> |
| Floor covering F L, Dirty, Cleaning | <b>25,00</b>  |




Bodywork, Not original part, Forfeit

**100,00**



Bonnet, Stone chip(s), LI - Repair and paint (complete)

217,56



Seat cover R R, Stain, Cleaning

25,00



Ceiling, Dirty, Cleaning

25,00



Bumper R, Hole, E - Replace

329,40

