


FORD Focus: 1HYE895

Vinnumber:	WF0KXXGCBKEM39346	Versionname:	FOCUS BER ECONetic T.Trend 95PK
First Registrationdate:	28/10/2014	Fiscalpower:	
Expertise Mileage:	119333	Power Kw:	70
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3117
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
Windows electric F		Luggage cover
Steering wheel multifunctional		Rear parking sensors
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/15/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1741,83
-------------------	---------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Windscreen, Scratch(es), E - Replace 0,00



Bumper Trim F, Broken, E - Replace 99,00



Sill outer R, Dent(s) and scratch(es), Le - Replace and paint 298,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display
Rearview mirror glass R, Broken, E - Replace 18,00



Rear window, Scratch(es), E - Replace 0,00



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35

