



VOLKSWAGEN PASSAT VARIANT: 1XMY423

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber: | VWVZZZ3CZFE439001 | Versionname: | 1.6 TDI VARIANT COMFORTLINE |
| First Registrationdate: | 28/04/2015 | Fiscalpower: | |
| Expertise Mileage: | 178451 | Power Kw: | 88 |
| Bodytype: | | Body color: | Light Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3714 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | SD | Central consol F | |
| GPS storage | | Luggage cover | |
| Windows electric F | | Front parking sensors | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|-----------------------|-------|-----------------------|
| 215/60/16/99 MS LightMetal | | | | |
| Summer tyres: | Fr.L. | Goodyear: 2 mm | Fr.R. | Goodyear: 3 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 729,92 |
|-------------------|---------------|

| | |
|--------------------------------------|--------------|
| Armrest F Mid, Damaged, Smart repair | 64,32 |
|--------------------------------------|--------------|



Windscreen, Stone chip(s), Windscreen repair 58,80



Rocker panel inner F L, Dent(s), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 25,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display