



VW Golf: 1GEE445

Vinnumber:	WVWZZZAUZEP057532	Versionname:	
First Registrationdate:	1/01/2014	Fiscalpower:	77
Expertise Mileage:	95062	Power Kw:	
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2214
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1742,08
-------------------	----------------

Interior, Worn, Acceptable	0,00
----------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Mirror side blinker R, Crack, E - Replace 30,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



GPS, Not functioning (well), P - Check 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 406,50



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining L, Broken, E - Replace 14,85




Engine, Maintenance, Execute 0,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Wing R R, Dent(s) and scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 100,00



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bad repair, Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00

