



RENAULT Scenic: 1HET741

Vinnumber:	VF1JZ0R0251321828	Versionname:	SCENIC Life 95PK
First Registrationdate:	2/07/2014	Fiscalpower:	
Expertise Mileage:	78299	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4109
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	750,08
--------------------------	---------------

Wing R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 30,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08

