


RENAULT Espace: 1HUL878

Vinnumber:	VF1JKFHA651569711	Versionname:	ESPACE Alcantara 130PK
First Registrationdate:	7/10/2014	Fiscalpower:	
Expertise Mileage:	152098	Power Kw:	96
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4811
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/101 W LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2118,38
Windscreen washer L, Incomplete, E - Replace	111,38



Headrest R L, Tear, E - Replace	72,00
---------------------------------	-------



Ignition key, Broken, E - Replace	150,00
-----------------------------------	--------



Backrest cover R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Hole, Le - Replace and paint	766,80
--	--------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display