


HONDA CR-V: 1LUV544

Vinnumber:	SHSRE6700FU210695	Versionname:	1.6 I-DTEC 2WD LIFESTYLE
First Registrationdate:	10/12/2015	Fiscalpower:	
Expertise Mileage:	204729	Power Kw:	88
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3513
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/18/104 MS LightMetal			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	414,21
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display