



MINI : 1PCU686

Vinnumber:	WMWXN110302A17111	Versionname:	1.5 ONE D
First Registrationdate:	7/06/2016	Fiscalpower:	
Expertise Mileage:	124741	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3104
Battery functioning:	Yes		
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Luggage cover	
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/15/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			801,88
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Maintenance, Maintenance, Execute			0,00
-----------------------------------	--	--	-------------

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)			290,08
--	--	--	---------------

Wing, Scratch(es), LI - Repair and paint (complete)

207,50



Outer door handle F L, Missing, E - Replace

12,80



Headlight protector F L, Missing, E - Replace

37,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Windscreen, Stone chip(s), Windscreen repair

58,80

