



AUDI A1 SPORTBACK: 1LLY169

Vinnumber:	WAUZZZ8XXGB045607	Versionname:	1.6 TDI 85KW
First Registrationdate:	23/10/2015	Fiscalpower:	
Expertise Mileage:	122396	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4828
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1650,10
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

176,14



Outer door handle F R, Scratch(es), LI - Repair and paint (complete)

115,56



SD card, Missing, E - Replace

220,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Outer door handle R R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44






Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bad repair, LI - Repair and paint (complete) 241,34



Bonnet, Scratch(es), LI - Repair and paint (complete) 232,06



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display