



MERCEDES CLA: 1LUN262

Vinnumber:	WDD1173121N320775	Versionname:	1.5 CLA 180 CDI URBAN
First Registrationdate:	9/12/2015	Fiscalpower:	
Expertise Mileage:	93507	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4721
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/40/18/92 V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1373,21
--------------------------	----------------

Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Backrest cover F L, Dirty, Cleaning 25,00



Ignition key, Missing, E - Replace 150,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 312,21



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Xenon headlight R, Scratch(es), E - Replace	696,00
---	--------

