



Ford Grand C Max: 1CF0171

Vinnumber:	WF0HXXWPBHB079153	Versionname:	
First Registrationdate:	14/11/2011	Fiscalpower:	
Expertise Mileage:	23594	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2819
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/92 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	4384,05
-------------------	---------

Bumper Trim F, Dent(s) and scratch(es), E - Replace	69,00
---	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 332,20



Wing F L, Dent(s) and scratch(es), Le - Replace and paint 530,02



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 414,35



Sill outer R, Not original part, E - Replace 174,00



Bumper F, Dent(s) and scratch(es), Le - Replace and paint 735,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Scratch(es), It - Spot repair 115,56



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 404,20



Rear window, Scratch(es), 67 - Polish 55,19



Wing R L, Crack, Le - Replace and paint 175,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display