


BMW X1: MU9295

Vinnumber:	WBAHT710305J34776	Versionname:	2.0 SDRIVE18D (110KW)
First Registrationdate:	22/03/2017	Fiscalpower:	
Expertise Mileage:	107810	Power Kw:	110
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4819
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Seats F L ventilated	
GPS storage	HD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Type of headlighting	Headlighting Xenon	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT		401,00
Door R R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper moulding R, Crack, E - Replace		17,28



Bumper moulding R R, Deformed / Strained, E - Replace

17,28



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper moulding F, Scratch(es), E - Replace

17,28



Door F L, Dent(s), Acceptable

0,00

No pictures to display