



**AUDI A6 AVANT: 1JTT431**

Vinnumber:	<b>WAUZZZ4G1FN064212</b>	Versionname:	<b>3.0 TDI 155KW S TRONIC QUATTRO</b>
First Registrationdate:	<b>24/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>198411</b>	Power Kw:	<b>155</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3511</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>BF Goodrich: 4 mm</b>	Fr.R.	<b>BF Goodrich: 4 mm</b>
	Re.L.	<b>BF Goodrich: 4 mm</b>	Re.R.	<b>BF Goodrich: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>1416,80</b>
<b>Door R L, Scratch(es), LI - Repair and paint (complete)</b>	<b>382,02</b>



Door F L, Scratch(es), LI - Repair and paint (complete)

382,02



Dashboard, Glue residues, Acceptable

0,00



Wheel arch cover F R, Broken, E - Replace

27,84



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)


95,00



Wing F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Door F R, Dent(s), Acceptable 0,00

*No pictures to display*

Windscreen, Stone chip(s), Acceptable 0,00



Rearview mirror glass L, Missing, E - Replace 21,60

