



AUDI A3 SPORTBACK: 1PBU109

Vinnumber:	WAUZZZ8V9GA167542	Versionname:	1.6 TDI 81KW ATTRACTION
First Registrationdate:	31/05/2016	Fiscalpower:	
Expertise Mileage:	50433	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4804
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1487,10
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), E - Replace			235,20




Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre F R, Deformed / Strained, E - Replace 132,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Alloy rim F R, Scratch(es), E - Replace 235,20

