



BMW 5 GRAN TURISMO: 1LPK985

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnnumber: | WBA5N21090G266347 | Versionname: | 2.0 520D (135KW) AUTO GRAN TURISMO |
| First Registrationdate: | 5/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 104355 | Power Kw: | 135 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2721 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | HD | Seats electric F R | |
| GPS storage | | Sun Roof electric | |
| Windows electric F | | Panoramic roof | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Front parking sensors | |
| Seats F heated | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Head-up Display | | | |
| Adaptive cruise control | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
| | 245/50/18/100 H LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | | |
|--|----------------|------------|
| | Runflat | Yes |
|--|----------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 254,16 |
|-------------------|---------------|

| | |
|---|---------------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|---------------|



| | |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |