



BMW 1 HATCH: 1NHT824

Vinnumber:	WBA1S510305A86479	Versionname:	2.0 118D (100KW)
First Registrationdate:	29/02/2016	Fiscalpower:	
Expertise Mileage:	122692	Power Kw:	100
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3826
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1385,10
-------------------	---------

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------



Rear wiper blade, Tear, Acceptable 0,00



Windscreen, Stone chip(s), Acceptable 0,00
No pictures to display


Wing F L, Chemical polution, 67 - Polish 0,00



Tyre F R, Tear, E - Replace 132,00



Tailgate, Dent(s), PDR - Painless dent repair 63,00



Door panel F L, Scratch(es), Acceptable 0,00
No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Stone chip(s), Acceptable 0,00
No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



