



BMW 3 TOURING: 1PJG635

Vinnumber:	WBA8H71050K833121	Versionname:	2.0 318D (110KW) TOURING
First Registrationdate:	13/07/2016	Fiscalpower:	
Expertise Mileage:	98147	Power Kw:	110
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2533
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 MS LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			904,40
Door R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F L, Scratch(es), It - Spot repair			115,56



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Smart repair 110,64



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00

