


MERCEDES GLC: AM9291

Vinnumber:	WDC2539051F022947	Versionname:	2.1 GLC 220 D 120KW 4M LAUNCH EDITION
First Registrationdate:	9/11/2015	Fiscalpower:	120
Expertise Mileage:	185010	Power Kw:	Grey
Bodytype:	Automatic	Body color:	Metalic
Gearbox:	Automatic	Paint type:	Aluminium
Transmission:	4 Weel	Rims summer:	OK
Fueltype:	Diesel	Oil level:	3509
Maintenance:	OK	Parking lot:	
Maintenance:	SERV BH BINNEN 18600KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining semi-Alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/55/19/105 V LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	308,00
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Sidewall panel RR, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Backrest cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror basis R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Stone chip(s), Acceptable 0,00

No pictures to display

Door panel F R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Scratch(es), Acceptable 0,00

No pictures to display

Sidewall panel RL, Scratch(es), Acceptable 0,00

No pictures to display