


**BMW 3 TOURING: 1JXH362**

Vinnumber:	<b>WBA3K11080F838363</b>	Versionname:	<b>2.0 318D (100KW) TOURING</b>
First Registrationdate:	<b>12/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>181577</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4309</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

**Assistance equipment**

	<b>Runflat</b>	<b>Yes</b>
Total cost ex VAT		<b>1649,66</b>
Backrest cover R R, Scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		<b>0,00</b>



Tailgate, Scratch(es), Acceptable 0,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), I - Repair 100,00



Alloy rim R L, Scratch(es), I - Repair 100,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), Acceptable 0,00



Door panel R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Sill trim R, Scratch(es), LI - Repair and paint (complete) 275,00





Alloy rim F R, Scratch(es), I - Repair 100,00



Shutter / cover, Broken, E - Replace 99,71



Windscreen, Stone chip(s), Windscreen repair 58,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Shutter / cover, Missing, E - Replace 14,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), Acceptable 0,00

