



BMW 4 GRAN COUPE: 1NFP265

Vinnumber:	WBA4E91000G289620	Versionname:	2.0 420D (120KW) GRAN COUPE
First Registrationdate:	12/02/2016	Fiscalpower:	
Expertise Mileage:	119285	Power Kw:	120
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4123
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 V LightMetal				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	349,16
--------------------------	---------------

Door panel trim R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Tailgate, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Mats, Tear, Acceptable	0,00
------------------------	-------------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel trim R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Bad repair, Acceptable

0,00

No pictures to display