


MERCEDES B 180: 1HVP068

Vinnumber:	WDD2462121J290497	Versionname:	CDI
First Registrationdate:	14/10/2014	Fiscalpower:	
Expertise Mileage:	101154	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4508
Maintenance	A IN 213 DAYS		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			897,80
Wheel cover F R, Scratch(es), E - Replace			30,00



Wing R L, Bad repair, P - Check

0,00



Wheel cover F L, Scratch(es), E - Replace

30,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

30,00



Front end, Bad repair, P - Check

0,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Stain, Cleaning

100,00





Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	307,80
---	--------



Door F L, Bad repair, P - Check	0,00
---------------------------------	------



Headlight L, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Window R L door, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover R L, Missing, E - Replace	30,00
---------------------------------------	-------

