



**MINI : 1RFU718**

Vinnumber:	<b>WMWXN110903C77913</b>	Versionname:	<b>1.5 ONE D</b>
First Registrationdate:	<b>13/12/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>76149</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3505</b>
Maintenance:	<b>BINNEN 11000KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>3</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage:	<b>HD</b>	Luggage cover:	
GPS storage:		Type of Tow bar:	<b>No Tow bar</b>
Windows electric F:			
Alarm:			
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning:	<b>OK</b>	Battery functioning:	<b>Yes</b>
Tires wear profile:	<b>OK</b>	Power steering:	<b>Yes</b>
Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Wiper fluid level:	<b>OK</b>
Handbrake:	<b>OK</b>	Transmission:	<b>OK</b>
		Lighting:	<b>OK</b>
		Wiperblades:	<b>OK</b>

**Degree of wear**

	<b>175/65/15/84 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
-------------	------------	-------------	------------

Total cost ex VAT: 330,56

Seat cover F L, Stain, Cleaning: 25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display