



**FORD S Max: 1GHH993**

|                                    |                          |              |                                       |
|------------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnumber:                         | <b>WF05XXGBWSDE07987</b> | Versionname: | <b>S-MAX Titanium Style DPF 136PK</b> |
| First Registrationdate:            | <b>7/02/2014</b>         | Fiscalpower: |                                       |
| Expertise Mileage:                 | <b>164602</b>            | Power Kw:    | <b>100</b>                            |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>                           |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                        |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                      |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                             |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3602</b>                           |
| Number of doors:                   | <b>5</b>                 |              |                                       |
| Number of seats:                   | <b>5</b>                 |              |                                       |
| Number head rests:                 | <b>5</b>                 |              |                                       |
| Rims summer:                       | <b>Aluminium</b>         |              |                                       |
| Category:                          | <b>Passenger Car</b>     |              |                                       |
| Oil level:                         | <b>OK</b>                |              |                                       |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                       |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Seats electric F L    |                   |
| GPS storage                    | <b>HD</b>                    | Seats electric F R    |                   |
| GPS storage                    |                              | Central consol F      |                   |
| Windows electric F             |                              | Luggage cover         |                   |
| Windows electric R             |                              | Front parking sensors |                   |
| Cruise Control                 |                              | Rear parking sensors  |                   |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Seats F heated                 |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                     |       |                     |
|----------------------------------|-------|---------------------|-------|---------------------|
| <b>225/50/17/98 H LightMetal</b> |       |                     |       |                     |
| Winter tyres:                    | Fr.L. | <b>Dunlop: 4 mm</b> | Fr.R. | <b>Dunlop: 4 mm</b> |
|                                  | Re.L. | <b>Dunlop: 4 mm</b> | Re.R. | <b>Dunlop: 4 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 268,64 |
|-------------------|--------|

|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|                               |      |
|-------------------------------|------|
| Door F L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

*No pictures to display*

|  |       |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 63,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display