


OPEL INSIGNIA SPORTS TOURER: 1UGL601

Vinnumber:	W0VZM8EE5J1140898	Versionname:	1.6 CDTi ecoTEC D 81kW Edition S/S
First Registrationdate:	3/05/2018	Fiscalpower:	
Expertise Mileage:	38178	Power Kw:	81
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3203
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/17/94 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1441,30
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

0,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

0,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

0,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

414,35



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00




Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), LI - Repair and paint (complete)

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

