


RENAULT CLIO: 1XPX697

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | VF15R0J0A54168218 | Versionname: | 1.5 ENERGY DCI 90E EXPRESSION |
| First Registrationdate: | 10/12/2015 | Fiscalpower: | |
| Expertise Mileage: | 60484 | Power Kw: | 66 |
| Bodytype: | | Body color: | Red |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4614 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | | |
|--------------------------------|-------------------------------|----------------------|-------------------|
| GPS storage | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 185/65/15/92 T Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |


Assistance equipment

| | | | |
|------------------------------------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-------------------------------------------|---------|
| Total cost ex VAT | 2103,72 |
| Wheel cover R R, Scratch(es), E - Replace | 24,00 |



| | |
|-------------------------------------------------|--------|
| Door F L, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Certificate Of Conformity, Missing, E - Replace | 150,00 |
| <i>No pictures to display</i> | |
| Wheel cover F R, Scratch(es), E - Replace | 24,00 |



| | |
|------------------------------|------|
| Roof, Bad repair, Acceptable | 0,00 |
|------------------------------|------|



| | |
|-----------------------------------|------|
| Wing F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------------------------------------------------|--------|
| Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 254,68 |
|---------------------------------------------------------------------|--------|



| | |
|---------------------------------------------------------|--------|
| Door F R, Scratch(es), LI - Repair and paint (complete) | 254,68 |
|---------------------------------------------------------|--------|



| | |
|------------------------------------|-------|
| Interior, Dirty, Chemical cleaning | 50,00 |
|------------------------------------|-------|





Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover R L, Scratch(es), E - Replace

24,00



Wheel cover F L, Scratch(es), E - Replace

24,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Outer door handle F L, Scratch(es), LI - Repair and paint (complete)

115,56



Bonnet, Bad repair, Acceptable

0,00



Instrument panel cover, Worn, Acceptable 0,00



Registration Document, Missing, E - Replace 150,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56

