



PEUGEOT EXPERT: 1NJL050

Vinnumber:	VF3VFAKHJZ081373	Versionname:	
First Registrationdate:	18/12/2018	Fiscalpower:	
Expertise Mileage:	28645	Power Kw:	90
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV08
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/65/16/104 T Steel			
Summer tyres:	Fr.L. Michelin: 3 mm	Fr.R. Michelin: 3 mm	
	Re.L. Michelin: 4 mm	Re.R. Michelin: 4 mm	

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1436,08
--------------------------	----------------

Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
--	---------------



Interior, Dirty, Cleaning	100,00
----------------------------------	---------------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Ignition key, Missing, E - Replace

150,00

No pictures to display

Trunk door R L, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), Smart repair

110,64



Dashboard, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Door panel F R, Scratch(es), Acceptable

0,00

No pictures to display

Trunk door R R, Scratch(es), It - Spot repair

115,56



Door F R, Scratch(es), Acceptable

0,00

No pictures to display