



RENAULT ESPACE: 1KPZ718

Vinnumber:	VF1RFC00753159223	Versionname:	1.6 DCI 160 EDC ENERGY INITIALE PARIS
First Registrationdate:	12/06/2015	Fiscalpower:	
Expertise Mileage:	214487	Power Kw:	118
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3433
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

TV/DVD screen R	Seats R heated
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Tow bar fixed
Type of GPS	Headlighting LED
Type of Lining	GPS big screen color
Type of climate control	Lining artificial leather
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/19/92 H LightMetal			
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2192,83
-------------------	----------------

Interior, Dirty, Cleaning	0,00
---------------------------	-------------



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Repaired, Acceptable 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper trim R, Scratch(es), Acceptable 0,00


No pictures to display

Rearview mirror basis R, Missing, E - Replace 29,80



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56

