



**RENAULT CLIO: 1NEA700**

Vinnumber:	<b>VF15R0J0A54168189</b>	Versionname:	<b>1.5 ENERGY DCI 90E EXPRESSION</b>
First Registrationdate:	<b>2/02/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>88186</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4807</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/92 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1308,54</b>
Roof, Chemical polution, LI - Repair and paint (complete)	<b>385,20</b>





Door R L, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34



Central pillar L, Dent(s) and scratch(es), It - Spot repair 115,56



Windscreen, Stone chip(s), Windscreen repair 58,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wing moulding F R, Missing, E - Replace 11,52



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Bumper R, Crack, LI - Repair and paint (complete) 169,44



Wheel cover F L, Scratch(es), E - Replace 24,00



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Repaired, Acceptable 0,00

No pictures to display